

Material & Engineering Laboratory-Taipei

TEST REPORT

REPORT NO.: HV-11-05689X PAGE: 1 OF 3 DATE: SEPTEMBER 14, 2011

NANOSHINE LTD.

UNIT 1006, 10/FL.CARNARVON PLAZA, 20 CARNARVON ROAD, TSIMSHATSUI, HONG KONG.

The following merchandise was submitted and identified by the vendor as:

<u>Style/Item No.</u>: Ceramic PRO <u>Manufacturer/Vendor</u>: Nanoshine LTD.

Country of Origin: Taiwan

We have tested the submitted sample(s) as requested and the following results were obtained:

<u>Test Required</u>: (According to client's test specification, please see following sheets in detail.)

Hardness by Pencil Test

<u>Test Result</u>:

-PLEASE SEE ATTACHED PAGE-

Date of Receive : SEPTEMBER 01, 2011

Date of Testing: SEPTEMBER 01, 2011~ SEPTEMBER 06, 2011

Signed for and on behalf of SGS Taiwan Ltd.

Carlos Kao Asst. Manager

The content of this PDF file is accordance with the original issued reports for reference only. This Test Report cannot be reproduced, except in full, without prior written permission of the Company.此 PDF 電子檔內容係根據原簽發之紙本報告製作,僅供參考用。本報告未經本公司書面同意,不可部份複製。



Material & Engineering Laboratory-Taipei

TEST REPORT

REPORT NO.: HV-11-05689X

PAGE:

2

3


OF

DATE: SEPTEMBER 14, 2011

Hardness by Pencil Test

Test Equipment:

Name	Brand
Pencil	MITSU-BISHI uni



Lab Environmental Conditions:

Ambient Temperature: 23±2°C

Relative humidity: 50±5%RH

Test Method/ Specification:

JIS K5400(1990)

Testing Methods for Paints (Scratch Hardness)

The variety of pencil hardness:

Soft ←------→ Hard

Load:

1000 g

Test Result:

Above 9H

The content of this PDF file is accordance with the original issued reports for reference only. This Test Report cannot be reproduced, except in full, without prior written permission of the Company.此 PDF 電子檔內容係根據原簽發之紙本報告製作,僅供參考用。本報告未經本公司書面同意,不可部份複製。

SGS Taiwan Ltd.

| No.33, No.35, Wu Chyuan Road, Wuku Industrial Zone, Taipei County, Taiwan/台北縣五股工業區五權路 33 號, 35 號

公司 t (886-2) 2298-3355

f (886-2) 2299-7857

www.tw.sgs.com
Member of SGS Group




Material & Engineering Laboratory-Taipei

TEST REPORT

REPORT NO.: HV-11-05689X PAGE: 3 OF 3 DATE: SEPTEMBER 14, 2011

Test Photo:



- The End of Test Report -

The content of this PDF file is accordance with the original issued reports for reference only. This Test Report cannot be reproduced, except in full, without prior written permission of the Company.此 PDF 電子檔內容係根據原簽發之紙本報告製作,僅供參考用。本報告未經本公司書面同意,不可部份複製。

No.33, No.35, Wu Chyuan Road, Wuku Industrial Zone, Taipei County, Taiwan/台北縣五股工業區五權路 33 號, 35 號

SGS Taiwan Ltd.